

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1310 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1310 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010027

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Secondary Architectural Style: Ranch, Minimal

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: brick masonry; stucco, textured; wood, channel

Architectural Details: decorative wood elements

Roof

Roof Form: gable, side; shed

Roof Cladding: composition shingle

Roof Details: eaves, open; eaves, shallow; gable vent; exterior chimney, brick

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: flooring, tile; steps, tile; railing,

wood; planter(s), brick; posts, wood; light fixtures; entry roof

Primary Door Type & Material: single door; paneled; wood

Primary Door Details: security door

Windows

Window Grouping & Type 1: tripartite; fixed; casement

Window Materials 1: wood

Window Details 1: multi-light

Window Grouping & Type 2: single; casement

Window Materials 2: wood

Window Details 2: multi-light

Window Grouping & Type 3: paired; double-hung

Window Materials 3: wood

Window Details 3: multi-light

Related Features

Related Features: ancillary building(s); gate(s), metal; driveway, brick; driveway, concrete; walkway, tile; lawn

Alterations

Alterations: restuccoed, incompatible; windows replaced, some, secondary; porch flooring altered/replaced; security door added; window openings infilled, secondary; walkway altered; gate added/replaced; garage altered/replaced; driveway gate added/replaced

Character-defining Features: one story height, asymmetrical massing, channel wood siding, side gabled and shed roof with open eaves, shallow eaves, and gable vents, brick chimney, partial-width projecting porch with wood posts, paneled wood door, multi-light wood tripartite window, multi-light wood casement window, multi-light wood double-hung windows

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1939 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1315 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1315 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: set back
Height: 2-story
Plan: irregular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: stucco, textured

Roof

Roof Form: gable, front; hipped
Roof Cladding: composition shingle
Roof Details: dormer(s), vent roof; eaves, open; gable vent; exposed rafter tails

Entrance(s)

Primary Entry Type: stoop
Primary Entry Materials & Details: flooring, concrete; light fixtures; steps, concrete
Primary Door Type & Material: single door; partially glazed; wood

Windows

Window Grouping & Type 1: single; paired; single-hung
Window Materials 1: non-original material
Window Grouping & Type 2: single; sliding, horizontal
Window Materials 2: non-original material

Related Features

Related Features: garage, detached; gate(s), wood; driveway, concrete; lawn; side fence, wood; walkway, concrete

Alterations

Alterations: addition, rear; addition, upper story; windows replaced, all; wall cladding added/replaced; door replaced, primary; entrance altered, primary; driveway gate added/replaced; light fixture added/replaced; pergola added; garage door replaced; gate added/replaced

Character-defining Features: none identified

Integrity: low

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1940 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1316 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1316 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010028

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: set back
Height: 1-story
Plan: irregular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: stucco, textured

Roof

Roof Form: hipped
Roof Cladding: composition shingle
Roof Details: eaves, boxed; exterior chimney, brick

Entrance(s)

Primary Entry Type: stoop
Primary Entry Materials & Details: flooring, concrete; flooring, brick;
steps, concrete; steps, brick; light fixtures; posts, wood; awning
Primary Door Type & Material: single door; unknown/not visible
Primary Door Details: security door

Windows

Window Grouping & Type 1: single; paired; grouped; single-hung
Window Materials 1: non-original material
Window Grouping & Type 2: glass block; fixed
Window Materials 2: glass block

Related Features

Related Features: gate(s), metal; driveway, asphalt; walkway, concrete
pavers; lawn

Alterations

Alterations: windows replaced, all; windows replaced, some, primary;
window openings altered, primary; wall cladding added/replaced; porch
supports altered; driveway gate added/replaced; awning(s) added

Character-defining Features: one story height, asymmetrical
massing, hipped roof with boxed eaves, brick chimney, stoop

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1317 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1317 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth; wood, channel

Architectural Details: decorative wood elements

Roof

Roof Form: gable, side

Roof Cladding: composition shingle

Roof Details: eave returns; eaves, boxed; eaves, shallow; gable vent;

interior chimney, brick

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: fence, metal; handrail(s); railing,

metal; flooring, tile; steps, tile; light fixtures

Primary Door Type & Material: single door; paneled; wood

Windows

Window Grouping & Type 1: paired; single-hung

Window Materials 1: non-original material

Window Grouping & Type 2: single; fixed; porthole

Window Materials 2: wood

Window Details 2: leaded glass; multi-light; octagonal opening

Window Grouping & Type 3: single; fixed

Window Materials 3: non-original material

Related Features

Related Features: garage, detached; gate(s), metal; driveway, concrete;
lawn; walkway, brick

Alterations

Alterations: windows replaced, some, primary; windows replaced, some,
secondary; porch flooring altered/replaced; wall cladding
added/replaced; driveway gate added/replaced; gate added/replaced

Character-defining Features: one story height, asymmetrical
massing, channel wood siding, side gabled roof with eave returns,
boxed eaves, shallow eaves, and gable vents, partial-width projecting
porch, paneled wood door, multi-light wood fixed porthole window with
leaded glass and octagonal opening, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1940 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1318 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1318 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010031

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: set back
Height: 1-story
Plan: rectangular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: stucco, smooth
Architectural Details: stringcourse; applied decoration/ornamentation

Roof

Roof Form: hipped
Roof Cladding: composition shingle
Roof Details: interior chimney, brick; eaves, boxed

Entrance(s)

Primary Entry Type: partial-width porch, projecting
Primary Entry Materials & Details: flooring, concrete; steps, concrete;
railing, metal; handrail(s); light fixtures
Primary Door Type & Material: single door; paneled; wood

Windows

Window Grouping & Type 1: grouped; double-hung; bay, bowed
Window Materials 1: wood
Window Details 1: multi-light; bay roof, standing seam
Window Grouping & Type 2: single; double-hung
Window Materials 2: wood
Window Details 2: shutter(s), all

Related Features

Related Features: garage, detached; driveway, concrete; walkway,
concrete; lawn

Alterations

Alterations: wall cladding added/replaced

Character-defining Features: one story height, asymmetrical
massing, stringcourse, hipped roof with boxed eaves, brick
chimney, partial-width projecting porch, paneled wood door, multi-
light wood bowed bay window, wood double-hung windows with
shutters, detached garage

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1320 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1320 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010019

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: tower volume

Roof

Roof Form: gable, cross; flat; hipped

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, closed; eaves, shallow; gable vent; parapet, flat

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: flooring, concrete; steps, concrete;

railing, metal; light fixtures; arch(es); entry roof

Primary Door Type & Material: single door; unknown/not visible

Primary Door Details: arched; security door

Windows

Window Grouping & Type 1: tripartite; fixed; casement

Window Materials 1: wood

Window Grouping & Type 2: grouped; casement

Window Materials 2: wood

Window Details 2: arched opening(s), round

Window Grouping & Type 3: single; double-hung

Window Materials 3: wood

Related Features

Related Features: garage, detached; driveway, concrete pavers

Alterations

Alterations: windows replaced, all; restuccoed, compatible; entrance altered, primary; porch flooring altered/replaced; driveway altered; front setback paved; driveway gate added/replaced; gate added/replaced; garage door replaced; security door added

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled, flat, and hipped roof with clay barrel tile cladding, clay tile coping, closed eaves, shallow eaves, gable vents, and flat parapet, partial-width projecting porch with arch

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1926 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1325 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1325 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009014

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

* **General Fields**

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Tudor Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: arch(es); wing wall

Roof

Roof Form: gable, cross; flat

Roof Cladding: clay barrel tile; composition shingle; material unknown

Roof Details: clay tile coping; parapet, flat; eaves, open; eaves, flared;

exposed rafter tails; gable vent; exterior chimney, stucco

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: flooring, concrete; low wall, stucco;

steps, concrete; awning; light fixtures

Primary Door Type & Material: single door; partially glazed; wood

Secondary Entry Type: stoop

Secondary Entry Materials & Details: flooring, concrete; handrail(s);

railing, wood; steps, concrete

Secondary Door Type & Material: single door; partially glazed;

paneled; wood

Windows

Window Grouping & Type 1: tripartite; fixed; single-hung

Window Materials 1: non-original material

Window Grouping & Type 2: single; jalousie/louver; sliding, horizontal

Window Materials 2: non-original material

Window Grouping & Type 3: single; double-hung

Window Materials 3: wood

Related Features

Related Features: garage, detached; gate(s), wood; driveway, concrete;
lawn; walkway, concrete

Alterations

Alterations: windows replaced, some, primary; windows replaced, some,
secondary; restuccoed, compatible; garage door replaced; awning(s)
added; driveway gate added/replaced; gate added/replaced

Character-defining Features: one story height, asymmetrical massing,
stucco wall cladding, cross gabled and flat roof with flat parapet, open
eaves, flared eaves, exposed rafter tails, and gable vents, stucco
chimney, wing wall with arched opening, partial-width projecting porch
with stucco wall, partially glazed wood door, wood double-hung windows

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1926 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

CONTINUATION SHEET

Property Name: 1325 Idlewood Rd

Page 2 of 2

***P3a. Description Section:** (Continued from page 1):

Alterations

Alterations: windows replaced, some, primary; windows replaced, some, secondary; restuccoed, compatible; garage door replaced; awning(s) added; driveway gate added/replaced; gate added/replaced

DRAFT

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1328 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1328 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010017

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: applied decoration/ornamentation; pierced screen(s)

Roof

Roof Form: gable, cross; flat

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, closed; eaves, shallow; gable vent; parapet, flat

Entrance(s)

Primary Entry Type: partial-width porch, projecting; courtyard

Primary Entry Materials & Details: low wall, stucco; flooring, concrete;

steps, concrete; piers, stucco; light fixtures

Primary Door Type & Material: single door; partially glazed; wood

Windows

Window Grouping & Type 1: tripartite; fixed; casement

Window Materials 1: wood

Window Details 1: multi-light; arched opening(s), scalloped; surround(s), decorative

Window Grouping & Type 2: tripartite; fixed; casement

Window Materials 2: wood

Window Details 2: multi-light; arched opening(s), round

Window Grouping & Type 3: tripartite; fixed; casement

Window Materials 3: wood

Window Details 3: multi-light

Related Features

Related Features: garage, detached; driveway, concrete; driveway, concrete ribbon; walkway, concrete; mature vegetation; gate(s), wood

Alterations

Alterations: appears to be unaltered

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, pierced screens, cross gabled and flat roof with clay barrel tile cladding, clay tile coping, closed eaves, shallow eaves, gable vents, and flat parapet, partial-width projecting porch, entrance courtyard with stucco wall and stucco piers, partially glazed wood door, multi-light wood tripartite window with scalloped arched opening, multi-light wood tripartite window with round arched opening, multi-light wood tripartite window, detached garage, concrete ribbon driveway

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1928 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1329 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1329 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Ranch, Minimal

Building Envelope

Setting: set back

Height: 1-story

Plan: rectangular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth; brick masonry

Roof

Roof Form: hipped

Roof Cladding: composition shingle

Roof Details: eaves, boxed; dormer(s), vent roof; interior chimney, brick

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: decorative supports; handrail(s); railing, metal; flooring, concrete; steps, concrete; light fixtures

Primary Door Type & Material: single door; partially glazed; paneled; wood

Windows

Window Grouping & Type 1: grouped; single-hung; bay, canted

Window Materials 1: vinyl

Window Details 1: bulkhead

Window Grouping & Type 2: single; double-hung

Window Materials 2: wood

Window Details 2: multi-light

Window Grouping & Type 3: single; fixed

Window Materials 3: wood

Window Details 3: obscure glass; shutter(s), all

Related Features

Related Features: garage, detached; driveway, concrete; gate(s), wood

Alterations

Alterations: windows replaced, some, primary; awning(s) added; decorative elements added; driveway gate added/replaced

Character-defining Features: one story height, asymmetrical massing, stucco and brick masonry wall cladding, hipped roof with boxed eaves and vent roof dormers, brick chimney, stoop with decorative supports, partially glazed and paneled wood door, multi-light wood double-hung windows, wood fixed window with obscure glass and shutters, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1947 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1333 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1333 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009016

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: No Style

Building Envelope

Setting: set back

Height: 2-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: balcony(ies)

Roof

Roof Form: flat; shed

Roof Cladding: composition shingle; material unknown

Roof Details: eaves, closed; parapet, flat

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: entry roof; flooring, concrete; steps, concrete; railing, metal; handrail(s); light fixtures

Primary Door Type & Material: single door; partially glazed; paneled; wood

Secondary Entry Type: stoop

Secondary Entry Materials & Details: flooring, concrete; steps, concrete; light fixtures

Secondary Door Type & Material: single door; paneled; wood

Windows

Window Grouping & Type 1: single; sliding, horizontal

Window Materials 1: vinyl

Window Grouping & Type 2: single; greenhouse

Window Materials 2: vinyl

Window Grouping & Type 3: single; fixed

Window Materials 3: vinyl

Related Features

Related Features: garage, detached; driveway, concrete ribbon; lawn; retaining wall, stucco; walkway, concrete

Alterations

Alterations: completely altered

Character-defining Features: none identified

Integrity: low

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1927 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1334 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1334 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Tudor Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, textured

Architectural Details: half-timbering; decorative wood elements

Roof

Roof Form: gable, cross; flat; shed; conical

Roof Cladding: composition shingle; material unknown

Roof Details: eaves, closed; eaves, shallow; exterior chimney, brick;

gable vent; parapet, flat; tower(s); weathervane

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: flooring, brick; decorative beams;

posts, wood; brackets; light fixtures; entry roof

Primary Door Type & Material: single door; partially glazed; paneled; wood

Windows

Window Grouping & Type 1: tripartite; fixed; casement

Window Materials 1: wood

Window Details 1: multi-light; diamond pane; awning(s)

Window Grouping & Type 2: single; grouped; casement

Window Materials 2: wood

Window Details 2: multi-light; diamond pane

Window Grouping & Type 3: grouped; fixed; casement; bay, canted

Window Materials 3: non-original material

Window Details 3: bay roof, composition shingle

Related Features

Related Features: garage, detached; driveway, concrete; driveway, brick; lawn

Alterations

Alterations: restuccoed, compatible; windows replaced, some, secondary; door replaced, primary; awning(s) added

Character-defining Features: one story height, stucco wall cladding, half-timbering, cross gabled, flat, and shed roof with closed eaves, shallow eaves, gable vents, flat parapet, and tower with conical roof and weathervane, brick chimney, partial-width projecting porch with decorative beams, wood posts, and brackets, multi-light wood tripartite window with diamond panes, multi-light wood casement windows with diamond panes, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1928 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 1337 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1337 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009017

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: arch(es); wing wall; tower volume

Roof

Roof Form: gable, cross; flat; conical

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, closed; gable vent; parapet, flat; parapet, shaped; exterior chimney, stucco; chimney pots

Entrance(s)

Primary Entry Type: stoop; tower

Primary Entry Materials & Details: arch(es); flooring, concrete; steps, concrete; light fixtures

Primary Door Type & Material: single door; paneled; wood

Primary Door Details: arched; speakeasy

Secondary Entry Type: stoop

Secondary Entry Materials & Details: flooring, concrete; steps, concrete; handrail(s); railing, metal; awning

Secondary Door Type & Material: single door; partially glazed; paneled; wood

Windows

Window Grouping & Type 1: single; fixed

Window Materials 1: wood

Window Details 1: arched opening(s), scalloped; multi-light; surround(s), decorative

Window Grouping & Type 2: fixed; tripartite; casement

Window Materials 2: wood

Window Details 2: multi-light; arched opening(s), segmental; surround(s), decorative

Window Grouping & Type 3: single; casement

Window Materials 3: wood

Window Details 3: arched opening(s), round

Continued on page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1928 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

CONTINUATION SHEET

Property Name: 1337 Idlewood Rd

Page 2 of 2

***P3a. Description Section:** (Continued from page 1):

Related Features

Related Features: garage, detached; driveway, concrete ribbon; lawn; retaining wall, concrete; walkway, concrete

Alterations

Alterations: restuccoed, compatible; window surrounds altered; security window bars added; windows replaced, some, secondary; awning(s) added; garage door replaced

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled and flat roof with clay barrel tile cladding, clay tile coping, closed eaves, gable vents, flat parapet, and shaped parapet, tower volume with conical roof, stucco chimney with chimney pots, stoop with arched opening within tower volume, arched and paneled wood door with speakeasy, multi-light wood fixed window with scalloped arched opening, multi-light wood tripartite window with segmental arched opening, wood casement window with round arched opening, concrete ribbon driveway

Integrity: moderate

DRAFT

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1338 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1338 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, textured

Architectural Details: wing wall; grilles, metal

Roof

Roof Form: gable, front; flat; shed

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, closed; eaves, shallow; gable

vent; parapet, flat; exterior chimney, stucco

Entrance(s)

Primary Entry Type: partial-width porch, recessed

Primary Entry Materials & Details: arch(es); flooring, concrete; steps, concrete; posts, wood

Primary Door Type & Material: single door; plank door; wood

Primary Door Details: speakeasy; grille

Windows

Window Grouping & Type 1: grouped; fixed; casement

Window Materials 1: wood

Window Details 1: multi-light; arched opening(s), round

Window Grouping & Type 2: grouped; fixed; casement

Window Materials 2: wood

Window Details 2: multi-light

Window Grouping & Type 3: single; single-hung

Window Materials 3: non-original material

Window Details 3: multi-light

Related Features

Related Features: garage, detached; gate(s), metal; driveway, concrete; walkway, concrete; lawn; mature vegetation

Alterations

Alterations: restuccoed, incompatible; windows replaced, some, primary; windows replaced, some, secondary; awning(s) added; driveway gate added/replaced

Character-defining Features: one story height, asymmetrical massing, front gabled, flat, and shed roof with clay barrel tile cladding, clay tile coping, closed eaves, shallow eaves, gable vents, and flat parapet, stucco chimney, wing wall, recessed partial-width porch with arches and wood posts, plank wood door with speakeasy and grille, multi-light wood fixed and casement windows with round arched openings, multi-light wood fixed and casement windows, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1927 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 1341 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1341 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009018

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: decorative wood elements

Roof

Roof Form: gable, cross; flat; shed

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, open; exposed rafter tails; gable vent; parapet, flat; exterior chimney, brick

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: entry gate; flooring, tile; steps, tile;

light fixtures; railing, metal; entry roof

Primary Door Type & Material: single door; paneled; wood

Primary Door Details: speakeasy

Secondary Entry Type: stoop

Secondary Entry Materials & Details: flooring, tile; steps, tile;

handrail(s); entry roof

Secondary Door Type & Material: unknown/not visible

Secondary Door Details: unknown/not visible

Windows

Window Grouping & Type 1: single; fixed

Window Materials 1: vinyl

Window Details 1: faux divided light(s)

Window Grouping & Type 2: tripartite; fixed; casement

Window Materials 2: vinyl

Window Details 2: faux divided light(s)

Window Grouping & Type 3: single; single-hung

Window Materials 3: vinyl

Related Features

Related Features: garage, detached; gate(s), metal; driveway, concrete pavers; fountain; side fence, metal; walkway, concrete pavers

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

(Continued on page 2)

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1932 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

CONTINUATION SHEET

Property Name: 1341 Idlewood Rd

Page 2 of 2

***P3a. Description Section:** (Continued from page 1):

Alterations

Alterations: windows replaced, all; light fixture added/replaced; porch flooring altered/replaced; wall or fence added, side; driveway gate added/replaced; driveway altered; walkway altered

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled, flat, and shed roof with clay barrel tile cladding, clay tile coping, open eaves, exposed rafter tails, gable vents, and flat parapet, partial-width projecting porch, paneled wood door with speakeasy, detached garage

Integrity: moderate

DRAFT

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1342 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1342 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010011

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Tudor Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, textured

Roof

Roof Form: gable, cross; flat; cat slide

Roof Cladding: composition shingle; clay barrel tile; material unknown

Roof Details: clay tile coping; gable vent; eaves, closed; eaves, flared; eaves, shallow

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: flooring, concrete; steps, concrete; handrail(s); awning; light fixtures; low wall, stucco; low wall, brick; arch(es)

Primary Door Type & Material: single door; partially glazed; paneled; wood

Windows

Window Grouping & Type 1: tripartite; fixed; casement

Window Materials 1: wood

Window Details 1: multi-light; awning(s)

Window Grouping & Type 2: paired; casement

Window Materials 2: wood

Window Details 2: multi-light

Window Grouping & Type 3: single; double-hung

Window Materials 3: wood

Window Details 3: awning(s)

Related Features

Related Features: garage, detached; driveway, concrete ribbon; driveway, concrete; walkway, concrete; lawn; planter(s), brick

Alterations

Alterations: awning(s) added; porch supports altered; wall cladding added/replaced

Character-defining Features: one story height, asymmetrical massing, cross gabled, flat, and cat slide roof with gable vents, closed eaves, flared eaves, and shallow eaves, partial-width projecting porch with stucco wall and arches, partially glazed and paneled wood door, multi-light wood tripartite window, multi-light wood casement windows, wood double-hung windows, detached garage, concrete ribbon driveway

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1928 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 1347 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1347 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009019

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Tudor Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, textured

Architectural Details: arch(es); wing wall

Roof

Roof Form: gable, cross; flat

Roof Cladding: clay barrel tile; composition shingle; material unknown

Roof Details: clay tile coping; eaves, open; exposed rafter tails;

parapet, flat; gable vent; exterior chimney, stucco

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: decorative supports; flooring, tile;

steps, tile; light fixtures; low wall, stucco; entry gate; awning

Primary Door Type & Material: single door; partially glazed; paneled; wood

Secondary Entry Type: stoop

Secondary Entry Materials & Details: flooring, tile; steps, tile; light

fixtures; awning

Secondary Door Type & Material: single door; unknown/not visible

Secondary Door Details: security door

Windows

Window Grouping & Type 1: grouped; fixed; single-hung

Window Materials 1: non-original material

Window Grouping & Type 2: single; fixed

Window Materials 2: non-original material

Window Grouping & Type 3: single; sliding, horizontal

Window Materials 3: non-original material

Related Features

Related Features: ancillary building(s); lawn; walkway, concrete;

driveway, brick; driveway, concrete; gate(s), metal

(Continued on page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1926 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

CONTINUATION SHEET

Property Name: 1347 Idlewood Rd

Page 2 of 2

***P3a. Description Section:** (Continued from page 1):

Alterations

Alterations: windows replaced, all; restuccoed, compatible; awning(s) added; garage altered/replaced; security door added; window openings altered, secondary; window openings infilled, secondary; porch flooring altered/replaced; porch supports altered; gate added/replaced

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled and flat roof with open eaves, exposed rafter tails, flat parapet, and gable vents, stucco chimney, wing wall with arched opening, partial-width projecting porch, partially glazed and paneled wood door

Integrity: moderate

DRAFT

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 1348 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1348 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010009

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)


* **General Fields**
Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Spanish Colonial Revival
Building Envelope
Setting: set back
Height: 1-story
Plan: irregular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: stucco, smooth
Architectural Details: tower volume; applied decoration/ornamentation
Roof
Roof Form: gable, cross; flat; shed; hipped
Roof Cladding: clay barrel tile; material unknown
Roof Details: clay tile coping; parapet, flat; eaves, closed; eaves, shallow
Entrance(s)
Primary Entry Type: partial-width porch, projecting
Primary Entry Materials & Details: flooring, concrete; steps, concrete;
awning; decorative supports; railing, metal; handrail(s); light fixtures
Primary Door Type & Material: single door; plank door; partially glazed; wood
Primary Door Details: security door

Windows
Window Grouping & Type 1: tripartite; fixed; casement
Window Materials 1: wood
Window Details 1: multi-light; arched opening(s), scalloped; surround(s), decorative
Window Grouping & Type 2: tripartite; fixed; casement
Window Materials 2: wood
Window Details 2: multi-light
Window Grouping & Type 3: grouped; casement
Window Materials 3: wood
Window Details 3: multi-light; arched opening(s), round; surround(s), decorative
Related Features
Related Features: garage, detached; driveway, concrete; walkway, concrete; lawn; mature vegetation; gate(s), metal
Alterations
Alterations: windows replaced, some, secondary; awning(s) added; decorative elements added; porch supports altered; railings altered/replaced; driveway gate added/replaced; security door added
Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled, flat, and shed roof with clay barrel tile cladding, clay tile coping, flat parapet, closed eaves, and shallow eaves, tower volume with hipped roof, partial-width projecting porch, partially glazed plank wood door, multi-light wood tripartite window with scalloped arched opening, multi-light wood tripartite window, multi-light wood casement windows with round arched openings, detached garage
Integrity: moderate

* P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1928 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)
☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1351 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1351 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009020

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

* **General Fields**

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, textured

Architectural Details: applied decoration/ornamentation

Roof

Roof Form: gable, cross; shed; flat

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, closed; interior chimney, brick;

gable vent; parapet, shaped

Entrance(s)

Primary Entry Type: partial-width porch, recessed

Primary Entry Materials & Details: arch(es); steps, concrete; flooring,

concrete; piers, stucco; low wall, stucco; light fixtures

Primary Door Type & Material: single door; partially glazed; paneled;

wood

Secondary Entry Type: stoop

Secondary Entry Materials & Details: light fixtures; steps, concrete;


flooring, concrete; awning

Secondary Door Type & Material: single door; paneled; wood

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1927 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1352 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1352 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010007

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

* **General Fields**

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Roof

Roof Form: gable, cross; flat; shed

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; parapet, flat; eaves, open; exposed rafter tails; gable vent

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: flooring, brick; steps, brick; railing, metal; handrail(s)

Primary Door Type & Material: single door; paneled; wood

Primary Door Details: security door

Windows

Window Grouping & Type 1: tripartite; fixed; double-hung

Window Materials 1: wood

Window Details 1: multi-light; awning(s)

Window Grouping & Type 2: single; paired; double-hung

Window Materials 2: wood

Window Details 2: multi-light; awning(s)

Window Grouping & Type 3: single; sliding, horizontal

Window Materials 3: non-original material

Related Features

Related Features: garage, detached; driveway, concrete; walkway, brick; lamppost; lawn

Alterations

Alterations: windows replaced, some, secondary; restuccoed, compatible; door replaced, primary; security door added; railings altered/replaced; garage door replaced; decorative elements added; awning(s) added

Related Features

Related Features: garage, detached; driveway, concrete; walkway, brick; lamppost; lawn

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled, flat, and shed roof with clay barrel tile cladding, clay tile coping, flat parapet, open eaves, exposed rafter tails, and gable vents, stoop, paneled wood door, multi-light wood tripartite window, multi-light wood double-hung windows

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1928 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1355 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1355 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628009021

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

* **General Fields**

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back
Height: 1-story
Plan: irregular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: stucco, textured
Architectural Details: applied decoration/ornamentation

Roof

Roof Form: gable, front; flat
Roof Cladding: clay barrel tile; material unknown
Roof Details: clay tile coping; gable vent; parapet, shaped; eaves, closed; exterior chimney, stucco

Entrance(s)

Primary Entry Type: partial-width porch, projecting
Primary Entry Materials & Details: flooring, concrete; steps, concrete;
low wall, stucco; light fixtures; entry roof
Primary Door Type & Material: single door; paneled; wood
Primary Door Details: carved
Secondary Entry Type: stoop
Secondary Entry Materials & Details: flooring, concrete; steps,
concrete; light fixtures; awning
Secondary Door Type & Material: single door; partially glazed; wood

Windows

Window Grouping & Type 1: tripartite; fixed; casement
Window Materials 1: wood
Window Details 1: multi-light
Window Grouping & Type 2: single; jalousie/louver
Window Materials 2: aluminum
Window Grouping & Type 3: single; casement
Window Materials 3: wood
Window Details 3: multi-light

Related Features

Related Features: garage, detached; driveway, concrete; walkway, concrete

Alterations

Alterations: window openings infilled, secondary; window surrounds altered; restuccoed, compatible; windows replaced, some, primary; windows replaced, some, secondary; door replaced, primary

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, front gabled and flat roof with clay barrel tile cladding, clay tile coping, gable vents, shaped parapet, and closed eaves, stucco chimney, partial-width projecting porch, multi-light wood tripartite window, multi-light wood casement window, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1926 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1358 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1358 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628010005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, textured

Architectural Details: decorative wood elements; applied decoration/ornamentation

Roof

Roof Form: gable, cross; shed; flat

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, open; exposed rafter tails; gable vent; parapet, flat; exterior chimney, stucco

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: posts, wood; decorative beams; flooring, tile; steps, tile; handrail(s); entry roof

Primary Door Type & Material: single door; paneled; wood

Windows

Window Grouping & Type 1: paired; casement

Window Materials 1: non-original material

Window Details 1: awning(s)

Window Grouping & Type 2: grouped; fixed; casement

Window Materials 2: non-original material

Window Grouping & Type 3: grouped; double-hung

Window Materials 3: wood

Window Details 3: awning(s)

Related Features

Related Features: garage, detached; driveway, concrete; walkway, tile; lawn

Alterations

Alterations: restuccoed, compatible; windows replaced, some, primary; windows replaced, some, secondary; awning(s) added; decorative tile added

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled, shed, and flat roof with clay barrel tile cladding, clay tile coping, open eaves, exposed rafter tails, gable vents, and flat parapet, stucco chimney, partial-width projecting porch with wood posts and decorative beams, paneled wood door, wood double-hung windows, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1929 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1400 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1400 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: corner; set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: brick masonry; stucco, smooth

Roof

Roof Form: hipped; shed

Roof Cladding: composition shingle

Roof Details: eaves, open; exposed rafter tails; exterior chimney, brick;

dormer(s), vent roof

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: flooring, concrete; steps, concrete;

light fixtures; entry roof

Primary Door Type & Material: single door; paneled; wood

Windows

Window Grouping & Type 1: single; single-hung

Window Materials 1: non-original material

Window Grouping & Type 2: single; sliding, horizontal

Window Materials 2: non-original material

Related Features

Related Features: garage, detached; driveway, concrete; walkway, concrete; lawn; flagpole

Alterations

Alterations: windows replaced, all; wall cladding added/replaced; porch flooring altered/replaced; light fixture added/replaced; gate added/replaced; walkway altered

Character-defining Features: one story height, asymmetrical massing, hipped and shed roof with open eaves, exposed rafter tails, vent roof dormers, brick chimney, stoop, paneled wood door, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1936 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1405 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1405 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: corner; not fully visible from public right-of-way; set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth; brick masonry

Roof

Roof Form: hipped

Roof Cladding: composition shingle

Roof Details: eaves, open; exposed rafter tails; exterior chimney, brick

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: flooring, brick; steps, brick; cheek

walls; handrail(s); railing, wood; posts, wood; light fixtures

Primary Door Type & Material: single door; partially glazed; paneled; wood

Windows

Window Grouping & Type 1: grouped; fixed; bay, bowed

Window Materials 1: wood

Window Details 1: multi-light; diamond pane; leaded glass; bay roof, composition shingle; bulkhead

Window Grouping & Type 2: paired; grouped; casement

Window Materials 2: steel

Window Details 2: multi-light; diamond pane; leaded glass

Window Grouping & Type 3: single; casement

Window Materials 3: wood

Window Details 3: multi-light

Related Features

Related Features: garage, detached; driveway, concrete; walkway, brick; steps, brick; retaining wall, stone; retaining wall, concrete; perimeter hedge(s); gate(s), wood; lawn; mature vegetation

Alterations

Alterations: garage door replaced; gate added/replaced; perimeter hedge(s) added

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, hipped roof with open eaves and exposed rafter tails, brick chimney, stoop with wood posts, partially glazed and paneled wood door, multi-light wood bowed bay window with diamond panes, leaded glass, and brick bulkhead, steel casement windows, multi-light wood casement window

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1940 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1406 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1406 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003011

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Secondary Architectural Style: Tudor Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: brick masonry; stucco, textured; stone, natural

Roof

Roof Form: hipped; shed

Roof Cladding: composition shingle

Roof Details: eaves, open; exposed rafter tails; exterior chimney, brick; exterior chimney, stucco

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: decorative supports; flooring, stone; posts, wood; steps, stone; light fixtures; entry roof

Primary Door Type & Material: single door; paneled; wood

Windows

Window Grouping & Type 1: grouped; fixed; bay, canted

Window Materials 1: wood

Window Details 1: multi-light; diamond pane; leaded glass; bay roof,

composition shingle; bulkhead

Window Grouping & Type 2: paired; casement

Window Materials 2: wood

Window Details 2: multi-light; diamond pane; leaded glass

Window Grouping & Type 3: single; paired; double-hung

Window Materials 3: wood

Window Details 3: multi-light

Related Features

Related Features: garage, detached; driveway, concrete; lawn; walkway, stone

Alterations

Alterations: wall cladding added/replaced; windows replaced, some, primary; windows replaced, some, secondary; porch flooring altered/replaced; walkway altered

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, hipped and shed roof with open eaves and exposed rafter tails, brick chimney, stucco chimney, stoop, paneled wood door, multi-light wood canted bay window with diamond panes, leaded glass, and bulkhead, multi-light wood casement windows with diamond panes and leaded glass, multi-light wood double-hung windows, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1409 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1409 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: grilles, metal

Roof

Roof Form: gable, cross

Roof Cladding: composition shingle

Roof Details: eaves, boxed; eave returns; eaves, shallow; gable vent;

interior chimney, stucco

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: columns; flooring, tile; steps, tile;

cheek walls; entry roof

Primary Door Type & Material: single door; fully glazed; wood

Primary Door Details: grille

Windows

Window Grouping & Type 1: single; single-hung

Window Materials 1: non-original material

Window Grouping & Type 2: single; sliding, horizontal

Window Materials 2: vinyl

Related Features

Related Features: driveway, concrete pavers; walkway, concrete pavers;
lawn; ancillary building(s)

Alterations

Alterations: porch flooring altered/replaced; windows replaced, all;
window openings altered, primary; window openings altered, secondary;
door replaced, primary; wall cladding added/replaced; shutters removed;
garage altered/replaced; garage door replaced

Character-defining Features: none identified

Integrity: low

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1939 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1414 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1414 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: set back
Height: 1-story
Plan: irregular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: stucco, smooth; stone, cut

Roof

Roof Form: hipped
Roof Cladding: composition shingle
Roof Details: eaves, open; exposed rafter tails; exterior chimney, brick;
dormer(s), vent roof

Entrance(s)

Primary Entry Type: partial-width porch, projecting
Primary Entry Materials & Details: flooring, stone; steps, stone; light
fixtures; awning; planter(s), stone
Primary Door Type & Material: single door; plank door; wood
Primary Door Details: speakeasy

Windows

Window Grouping & Type 1: single; fixed
Window Materials 1: wood
Window Details 1: multi-light; stained glass; oval opening
Window Grouping & Type 2: tripartite; casement; sliding, horizontal
Window Materials 2: non-original material
Window Grouping & Type 3: single; sliding, horizontal
Window Materials 3: non-original material

Related Features

Related Features: garage, detached; lamppost; driveway, concrete;
lawn; walkway, stone

Alterations

Alterations: windows replaced, all; wall cladding added/replaced; porch
flooring altered/replaced; light fixture added/replaced; garage door
replaced; awning(s) added; walkway altered

Character-defining Features: none identified

Integrity: low

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1415 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1415 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004006

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Minimal Traditional
Secondary Architectural Style: American Colonial Revival

Building Envelope

Setting: set back
Height: 1-story
Plan: irregular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: stucco, smooth
Architectural Details: decorative wood elements

Roof

Roof Form: hipped
Roof Cladding: composition shingle
Roof Details: eaves, boxed; interior chimney, brick; dormer(s), vent roof

Entrance(s)

Primary Entry Type: stoop
Primary Entry Materials & Details: flooring, stone; steps, stone; light fixtures
Primary Door Type & Material: single door; plank door; partially glazed; wood
Primary Door Details: surround, decorative

Windows

Window Grouping & Type 1: tripartite; fixed; single-hung
Window Materials 1: non-original material
Window Details 1: shutter(s), all
Window Grouping & Type 2: single; paired; single-hung
Window Materials 2: non-original material
Window Details 2: shutter(s), all

Related Features

Related Features: garage, detached; gate(s), wood; driveway, concrete; walkway, concrete; walkway, stone; driveway, stone

Alterations

Alterations: door replaced, primary; windows replaced, all; walkway altered; driveway gate added/replaced; light fixture added/replaced; visible solar panels; gate added/replaced

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, hipped roof with boxed eaves, vent roof dormers, brick chimney, stoop, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1418 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1418 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Secondary Architectural Style: American Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: rectangular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth; stone, cut

Architectural Details: decorative wood elements

Roof

Roof Form: hipped

Roof Cladding: composition shingle

Roof Details: eaves, boxed; interior chimney, pipe

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: steps, stone; flooring, stone; posts, wood; light fixtures

Primary Door Type & Material: single door; paneled; wood

Primary Door Details: speakeasy

Windows

Window Grouping & Type 1: grouped; casement; sliding, horizontal; bay squared

Window Materials 1: vinyl

Window Details 1: faux divided light(s); bay roof, standing seam;

bulkhead; shutter(s), all

Window Grouping & Type 2: grouped; sliding, horizontal

Window Materials 2: vinyl

Window Details 2: faux divided light(s); surround(s), decorative

Window Grouping & Type 3: single; sliding, horizontal

Window Materials 3: vinyl

Window Details 3: faux divided light(s); shutter(s), all

Related Features

Related Features: garage, detached; gate(s), metal; lamppost; driveway, concrete; lawn; walkway, stone

Alterations

Alterations: windows replaced, all; driveway gate added/replaced; wall cladding added/replaced; window surrounds altered; window openings altered, secondary

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, hipped roof with boxed eaves, chimney pipe, stoop with wood posts, paneled wood door with speakeasy, detached garage, lamppost

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List) _____

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1419 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1419 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: American Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: wood, clapboard; wood, beadboard

Architectural Details: decorative wood elements

Roof

Roof Form: gable, side; shed

Roof Cladding: composition shingle

Roof Details: eaves, open; exposed rafter tails; gable vent; interior chimney, brick

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: decorative supports; flooring, brick; steps, brick; light fixtures; entry roof

Primary Door Type & Material: single door; partially glazed; paneled; wood

Primary Door Details: fanlight

Windows

Window Grouping & Type 1: single; double-hung

Window Materials 1: wood

Window Details 1: multi-light; shutter(s), all

Window Grouping & Type 2: grouped; fixed; casement; bay, canted

Window Materials 2: wood

Window Details 2: multi-light; surround(s), decorative

Related Features

Related Features: ancillary building(s); gate(s), wood; driveway, concrete; walkway, brick

Alterations

Alterations: garage altered/replaced; no major alterations

Character-defining Features: one story height, asymmetrical massing, wood clapboard and wood beadboard siding, side gabled and shed roof with open eaves, exposed rafter tails, and gable vents, brick chimney, stoop with decorative supports, partially glazed and paneled wood door with fanlight, multi-light wood double-hung windows with shutters, multi-light wood canted bay window

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west. 4/4/2025

*P6. Date Constructed/Age and Sources 1939 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1423 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1423 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: applied decoration/ornamentation; wing wall; grilles, wrought iron

Roof

Roof Form: gable, cross; shed; pyramidal

Roof Cladding: clay barrel tile

Roof Details: clay tile coping; eaves, open; exposed rafter tails; gable vent; exterior chimney, stucco; tower(s)

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: flooring, concrete; steps, concrete; handrail(s); light fixtures; entry roof

Primary Door Type & Material: single door; plank door; wood

Primary Door Details: speakeasy

Windows

Window Grouping & Type 1: single; casement

Window Materials 1: non-original material

Window Grouping & Type 2: single; fixed

Window Materials 2: wood

Window Grouping & Type 3: single; double-hung

Window Materials 3: wood

Window Details 3: grille(s), wrought iron

Related Features

Related Features: garage, detached; driveway, concrete; driveway, concrete pavers; walkway, concrete; mature vegetation; gate(s), metal; gate(s), wood

Alterations

Alterations: windows replaced, some, primary; windows replaced, some, secondary; restuccoed, compatible; gate added/replaced


Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled and shed roof with clay barrel tile cladding, clay tile coping, open eaves, exposed rafter tails, gable vents, and tower with pyramidal roof, stucco chimney, wing wall, stoop, plank wood door with speakeasy, wood fixed window, wood double-hung window with wrought iron grilles, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1935 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1424 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1424 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: American Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: rectangular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: applied decoration/ornamentation; decorative wood elements

Roof

Roof Form: hipped

Roof Cladding: composition shingle

Roof Details: cornice; eaves, boxed; exterior chimney, brick; dormer(s), vent roof

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: flooring, brick; steps, brick; handrail(s); light fixtures; entry roof

Primary Door Type & Material: single door; paneled; wood

Primary Door Details: speakeasy

Windows

Window Grouping & Type 1: grouped; fixed; casement; bay, canted

Window Materials 1: wood

Window Details 1: multi-light; bay roof, standing seam; shutter(s), all

Window Grouping & Type 2: single; tripartite; double-hung

Window Materials 2: wood

Window Details 2: multi-light; shutter(s), some; surround(s), decorative

Window Grouping & Type 3: single; casement

Window Materials 3: wood

Window Details 3: multi-light

Related Features

Related Features: garage, detached; driveway, concrete; lawn; mature vegetation; walkway, brick

Alterations

Alterations: garage door replaced; no major alterations

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, hipped roof with cornice, boxed eaves, and vent roof dormers, brick chimney, stoop, paneled wood door with speakeasy, multi-light wood canted bay window, multi-light wood tripartite windows-some with shutters, multi-light wood casement window

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1427 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1427 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Tudor Revival

Building Envelope

Setting: set back; not fully visible from public right-of-way

Height: 1-story

Plan: rectangular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: half-timbering; decorative wood elements; grilles, metal

Roof

Roof Form: hipped; jerkinhead; gable, front

Roof Cladding: composition shingle

Roof Details: eaves, open; exposed rafter tails; exterior chimney,

stucco; exterior chimney, brick

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: flooring, brick; steps, brick; railing, metal; handrail(s); light fixtures

Primary Door Type & Material: single door; partially glazed; wood

Primary Door Details: grille

Windows

Window Grouping & Type 1: single; fixed

Window Materials 1: wood

Window Details 1: multi-light; diamond pane; leaded glass

Window Grouping & Type 2: single; awning

Window Materials 2: wood

Window Details 2: multi-light

Window Grouping & Type 3: paired; casement

Window Materials 3: wood

Related Features

Related Features: garage, detached; gate(s), metal; driveway, concrete; walkway, brick; lamppost; lawn

Alterations

Alterations: garage door replaced; no major alterations

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, half-timbering, hipped, jerkinhead, and front gabled roof with open eaves and exposed rafter tails, stucco and brick chimney, partial-width projecting porch, partially glazed wood door with grille, multi-light wood fixed window with diamond panes and leaded glass, multi-light wood awning window, wood casement windows, lamppost

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1927 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 1428 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1428 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Secondary Architectural Style: American Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: brick masonry; stucco, smooth

Architectural Details: decorative wood elements

Roof

Roof Form: hipped; gable, side

Roof Cladding: composition shingle

Roof Details: eaves, open; gable vent; exposed rafter tails; exterior chimney, brick

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: flooring, brick; steps, brick; posts, wood; light fixtures

Primary Door Type & Material: single door; paneled; wood

Primary Door Details: speakeasy

Secondary Entry Type: stoop

Secondary Entry Materials & Details: flooring, concrete; steps, concrete; awning; light fixtures

Secondary Door Type & Material: single door; partially glazed; paneled; wood

Windows

Window Grouping & Type 1: grouped; fixed; casement; bay, canted

Window Materials 1: non-original material

Window Details 1: bay roof, standing seam; shutter(s), all

Window Grouping & Type 2: paired; casement

Window Materials 2: non-original material

Window Details 2: shutter(s), all

Window Grouping & Type 3: single; casement

Window Materials 3: non-original material

Window Details 3: shutter(s), some

Related Features

Related Features: garage, detached; driveway, brick; driveway, concrete; lawn; walkway, concrete pavers; gate(s), metal

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

(Continued on page 2)

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1937 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

CONTINUATION SHEET

Property Name: 1428 Idlewood Rd

Page 2 of 2

***P3a. Description Section:** (Continued from page 1):

Alterations

Alterations: windows replaced, all; driveway gate added/replaced;
garage door replaced; wall or fence added, side; gate added/replaced

Character-defining Features: one story height, asymmetrical
massing, stucco and brick masonry wall cladding, hipped and side
gabled roof with open eaves, gable vents, and exposed rafter tails,
brick chimney, stoop with wood posts, paneled wood door with
speakeasy

Integrity: moderate

DRAFT

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1433 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1433 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth; brick masonry

Architectural Details: decorative wood elements; applied decoration/ornamentation; grilles, wrought iron

Roof

Roof Form: gable, side; flat; shed

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; parapet, flat; eaves, open; exposed rafter tails; exterior chimney, brick; exterior chimney, stucco

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: arcade; arch(es); flooring, tile; steps, tile; railing, metal; entry gate; light fixtures; low wall, stucco

Primary Door Type & Material: single door; plank door; wood

Primary Door Details: speakeasy

Windows

Window Grouping & Type 1: paired; casement

Window Materials 1: wood

Window Details 1: multi-light; grille(s), wrought iron; surround(s), decorative

Window Grouping & Type 2: single; double-hung

Window Materials 2: wood

Window Details 2: multi-light

Window Grouping & Type 3: single; casement

Window Materials 3: wood

Window Details 3: multi-light; shutter(s), all

Related Features

Related Features: garage, detached; porte cochere; driveway, concrete; driveway, brick; walkway, stone; walkway, brick; gate(s), wrought iron

Alterations

Alterations: walkway altered; grilles added/replaced; railings altered/replaced; no major alterations

Character-defining Features: one story height, asymmetrical massing, stucco and brick masonry wall cladding, side gabled, flat, and shed roof with clay barrel tile cladding, clay tile coping, flat parapet, open eaves, and exposed rafter tails, brick and stucco chimney, partial-width projecting porch with arcade, arches, and stucco wall, plank wood door with speakeasy, multi-light wood casement windows, multi-light wood double-hung windows, multi-light wood casement windows with shutters, porte cochere, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1934 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1435 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1435 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004017

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: applied decoration/ornamentation; decorative wood elements; wing wall

Roof

Roof Form: gable, cross; flat; shed

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; parapet, flat; interior chimney, stucco; eaves, open; exposed rafter tails; gable vent; exterior chimney, stucco

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: low wall, stucco; flooring, concrete; steps, concrete; light fixtures; decorative beams; posts, wood

Primary Door Type & Material: single door; partially glazed; wood

Windows

Window Grouping & Type 1: single; fixed

Window Materials 1: wood

Window Grouping & Type 2: tripartite; casement

Window Materials 2: wood

Window Details 2: multi-light

Window Grouping & Type 3: single; double-hung

Window Materials 3: wood

Window Details 3: multi-light, top sash

Related Features

Related Features: garage, detached; driveway, concrete pavers; gate(s), metal; lamppost; lawn; mature vegetation

Alterations

Alterations: restuccoed, compatible; porch flooring altered/replaced; windows replaced, some, secondary; driveway altered; driveway gate added/replaced; front setback paved

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, cross gabled, flat, and shed roof with clay barrel tile cladding, clay tile coping, flat parapet, open eaves, exposed rafter tails, and gable vents, stucco chimneys, partial-width projecting porch with stucco wall, decorative beams, and wood posts, partially glazed wood door, wood fixed window, multi-light wood tripartite window, wood double-hung window with multi-light top sash, detached garage, lamppost

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1927 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1436 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1436 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003006

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

* General Fields

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Minimal Traditional
Secondary Architectural Style: American Colonial Revival

Building Envelope

Setting: set back
Height: 1-story
Plan: rectangular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: brick masonry; stucco, smooth; wood, board-and-batten; wood, channel
Architectural Details: decorative wood elements

Roof

Roof Form: gable, side
Roof Cladding: composition shingle
Roof Details: eaves, closed; eaves, shallow; gable vent; exterior chimney, brick; cornice

Entrance(s)

Primary Entry Type: partial-width porch, recessed
Primary Entry Materials & Details: steps, stone; flooring, stone; posts, wood; light fixtures
Primary Door Type & Material: single door; paneled; wood
Secondary Entry Type: stoop
Secondary Entry Materials & Details: flooring, brick; flooring, concrete; light fixtures; awning
Secondary Door Type & Material: single door; slab door; wood

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1939 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2

*Resource Name or # (Assigned by recorder) 1440 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1440 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Secondary Architectural Style: American Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: L-shaped

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: brick masonry; stucco, smooth

Architectural Details: applied decoration/ornamentation; decorative wood elements; decorative brick elements

Roof

Roof Form: gable, side; hipped

Roof Cladding: composition shingle

Roof Details: eaves, boxed; eave returns; gable vent; exterior chimney, brick

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: flooring, brick; steps, brick; cheek

walls; light fixtures; surround, decorative

Primary Door Type & Material: single door; paneled; wood

Primary Door Details: speakeasy; surround, decorative

Secondary Entry Type: stoop

Secondary Entry Materials & Details: entry roof; brackets

Secondary Door Type & Material: unknown/not visible

Secondary Door Details: unknown/not visible

Windows

Window Grouping & Type 1: grouped; fixed; casement; bay, canted

Window Materials 1: wood

Window Details 1: multi-light; bay roof, standing seam; bulkhead

Window Grouping & Type 2: single; fixed; porthole

Window Materials 2: wood

Window Details 2: leaded glass; multi-light; surround(s), decorative

Window Grouping & Type 3: single; paired; double-hung

Window Materials 3: wood

Window Details 3: multi-light

Related Features

Related Features: garage, attached; driveway, concrete; lawn; walkway, brick pavers

(Continued on page 2)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View east, 4/4/2025

*P6. Date Constructed/Age and Sources 1936 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

CONTINUATION SHEET

Property Name: 1440 Idlewood Rd

Page 2 of 2

***P3a. Description Section:** (Continued from page 1):

Alterations

Alterations: garage door replaced; no major alterations

Character-defining Features: one story height, asymmetrical massing, brick masonry and stucco wall cladding, side gabled and hipped roof with boxed eaves, eave returns, and gable vents, brick chimney, stoop, paneled wood door with speakeasy, multi-light wood canted bay window with bulkhead, multi-light wood fixed porthole window with leaded glass, multi-light wood double-hung windows

Integrity: high

DRAFT

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1443 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1443 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004019

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back
Height: 1-story
Plan: irregular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: stucco, smooth; stone, cut
Architectural Details: grilles, metal

Roof

Roof Form: hipped
Roof Cladding: clay barrel tile
Roof Details: clay tile coping; eaves, open; exposed rafter tails

Entrance(s)

Primary Entry Type: stoop
Primary Entry Materials & Details: flooring, concrete; steps, concrete;
cheek walls; arch(es); light fixtures
Primary Door Type & Material: single door; fully glazed; metal
Primary Door Details: grille; sidelights

Windows

Window Grouping & Type 1: grouped; casement; bay, bowed
Window Materials 1: metal
Window Grouping & Type 2: single; paired; sliding, horizontal
Window Materials 2: metal

Related Features

Related Features: garage, integrated; gate(s), metal; driveway, concrete
pavers; lawn

Alterations

Alterations: completely altered

Character-defining Features: none identified

Integrity: low

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Primary # _____
HRI _____
Trinomial # _____
NRHP Status Code 5D1

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1446 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1446 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: brick masonry; stucco, smooth; wood, channel

Roof

Roof Form: hipped; shed

Roof Cladding: composition shingle

Roof Details: eaves, boxed; interior chimney, brick

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: posts, wood; flooring, brick; steps,

brick; light fixtures; entry roof

Primary Door Type & Material: single door; paneled; wood

Windows

Window Grouping & Type 1: grouped; fixed; single-hung; bay, canted

Window Materials 1: non-original material

Window Details 1: bay roof, composition shingle; bulkhead

Window Grouping & Type 2: tripartite; fixed; single-hung

Window Materials 2: non-original material

Window Grouping & Type 3: single; paired; single-hung

Window Materials 3: non-original material

Related Features

Related Features: garage, detached; gate(s), metal; driveway, concrete; lawn; planter(s), brick; walkway, concrete; gate(s), wood

Alterations

Alterations: windows replaced, all; restuccoed, compatible; driveway gate added/replaced; garage door replaced

Character-defining Features: one story height, asymmetrical massing, stucco and brick masonry wall cladding, channel wood siding, hipped and shed roof with boxed eaves, brick chimney, partial-width projecting porch with wood posts, paneled wood door

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1938 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1447 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1447 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004025

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth; stone, natural

Roof

Roof Form: gable, cross; shed; flat

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, open; exposed rafter tails; parapet, flat; exterior chimney, brick; exterior chimney, stucco

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: arcade; arch(es); flooring, concrete; steps, concrete; piers, stucco

Primary Door Type & Material: single door; plank door; wood

Primary Door Details: speakeasy

Secondary Entry Type: stoop

Secondary Entry Materials & Details: steps, concrete

Secondary Door Type & Material: single door; paneled; wood

Windows

Window Grouping & Type 1: single; fixed

Window Materials 1: wood

Window Details 1: multi-light

Window Grouping & Type 2: single; paired; casement

Window Materials 2: wood

Window Details 2: multi-light

Window Grouping & Type 3: single; sliding, horizontal

Window Materials 3: metal

Related Features

Related Features: garage, detached; porte cochere; driveway, concrete; walkway, concrete; lawn

Alterations

Alterations: windows replaced, some, primary; windows replaced, some, secondary; door replaced, secondary; wall or fence added, side; driveway gate added/replaced

Character-defining Features: one story height, asymmetrical massing, stucco and natural stone wall cladding, cross gabled, shed, and flat roof with clay barrel tile cladding, clay tile coping, open eaves, exposed rafter tails, and flat parapet, brick and stucco chimney, partial-width projecting porch with arcade, arches, and stucco piers, plank wood door with speakeasy, multi-light wood fixed window, multi-light wood casement windows, porte cochere, detached garage

Integrity: moderate

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1933 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1450 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1450 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003003

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential
Current Property Type: Single-family residential
Primary Architectural Style: Minimal Traditional
Secondary Architectural Style: American Colonial Revival

Building Envelope

Setting: set back
Height: 1-story
Plan: irregular
Primary Façade Composition: asymmetrical
Type of Construction: wood frame
Wall Cladding: brick masonry; stucco, smooth; wood, clapboard
Architectural Details: decorative wood elements

Roof

Roof Form: hipped
Roof Cladding: composition shingle
Roof Details: cornice; eaves, boxed; interior chimney, brick; chimney pots

Entrance(s)

Primary Entry Type: stoop
Primary Entry Materials & Details: flooring, brick; handrail(s); light fixtures; pilasters; steps, brick; surround, decorative
Primary Door Type & Material: single door; paneled; wood
Primary Door Details: speakeasy; surround, decorative

Windows

Window Grouping & Type 1: tripartite; grouped; double-hung; bay, canted
Window Materials 1: wood
Window Details 1: bay roof, composition shingle; bulkhead; multi-light
Window Grouping & Type 2: single; fixed; porthole
Window Materials 2: wood
Window Details 2: obscure glass; round opening
Window Grouping & Type 3: single; paired; grouped; double-hung
Window Materials 3: wood
Window Details 3: multi-light; shutter(s), some

Related Features

Related Features: garage, detached; driveway, concrete; lawn; planter(s), brick; driveway, brick; walkway, brick

Alterations

Alterations: driveway gate added/replaced; garage door replaced; railings altered/replaced; no major alterations

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, wood clapboard siding, hipped roof with cornice and boxed eaves, brick chimney with chimney pots, stoop with pilasters, paneled wood door with speakeasy, multi-light wood canted bay window with bulkhead, wood fixed porthole window with obscure glass and round opening, multi-light wood double-hung windows-some with shutters

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View west, 4/4/2025

*P6. Date Constructed/Age and Sources 1937 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1451 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles

and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____

c. Address 1451 Idlewood Rd City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004026

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

* **General Fields**

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: decorative wood elements

Roof

Roof Form: gable, side; flat; shed

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; parapet, flat; gable vent; exterior chimney, stucco; exterior chimney, brick; eaves, open; exposed rafter tails

Entrance(s)

Primary Entry Type: partial-width porch, projecting

Primary Entry Materials & Details: arcade; arch(es); flooring, concrete; steps, concrete

Primary Door Type & Material: unknown/not visible

Primary Door Details: unknown/not visible

Secondary Entry Type: stoop

Secondary Entry Materials & Details: steps, concrete; entry roof

Secondary Door Type & Material: single door; partially glazed; wood

Windows

Window Grouping & Type 1: single; fixed

Window Materials 1: wood

Window Details 1: multi-light; shutter(s), all; bay roof, standing seam

Window Grouping & Type 2: paired; casement

Window Materials 2: wood

Window Details 2: multi-light; shutter(s), all

Window Grouping & Type 3: single; casement

Window Materials 3: wood

Related Features

Related Features: garage, detached; porte cochere; driveway, concrete; driveway, brick; lawn; gate(s), wrought iron

Alterations

Alterations: awning(s) added; wall or fence added, side; no major alterations


Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, side gabled, flat, and shed roof with clay barrel tile cladding, clay tile coping, flat parapet, gable vents, open eaves, and exposed rafter tails, brick chimney, stucco chimney, partial-width projecting porch with arcade and arches, multi-light wood fixed window with shutters and bay roof, multi-light wood casement windows with shutters, wood casement window, porte cochere, detached garage

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1933 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1455 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1455 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628004027

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

General Fields

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Spanish Colonial Revival

Building Envelope

Setting: set back; not fully visible from public right-of-way

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: stucco, smooth

Architectural Details: decorative wood elements; applied decoration/ornamentation

Roof

Roof Form: gable, side; flat; shed

Roof Cladding: clay barrel tile; material unknown

Roof Details: clay tile coping; eaves, open; exposed rafter tails;

parapet, flat; exterior chimney, stucco

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: low wall, stucco; flooring, concrete;

steps, concrete; arch(es)

Primary Door Type & Material: unknown/not visible

Primary Door Details: unknown/not visible

Windows

Window Grouping & Type 1: single; fixed

Window Materials 1: wood

Window Details 1: multi-light; surround(s), decorative

Window Grouping & Type 2: single; paired; grouped; casement

Window Materials 2: wood

Window Details 2: multi-light

Related Features

Related Features: porte cochere; gate(s), wrought iron; ancillary building(s); driveway, concrete ribbon; walkway, gravel; lawn; mature vegetation; walkway, concrete stepping stones

Alterations

Alterations: garage altered/replaced; no major alterations

Character-defining Features: one story height, asymmetrical massing, stucco wall cladding, side gabled, flat, and shed roof with clay barrel tile cladding, clay tile coping, open eaves, exposed rafter tails, and flat parapet, stucco chimney, stoop with stucco wall and arch, multi-light wood fixed window, multi-light wood casement windows, porte cochere, concrete ribbon driveway

Integrity: high

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View southwest, 4/4/2025

*P6. Date Constructed/Age and Sources 1933 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)

PRIMARY RECORD

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1

*Resource Name or # (Assigned by recorder) 1458 Idlewood Rd

P1. Other Identifier: _____

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a.County Los Angeles
and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M. _____
c. Address 1458 Idlewood Rd City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____; _____ mE/ _____ mN _____
e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) APN 5628003002

P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting and boundaries)

* **General Fields**

Historic Property Type: Single-family residential

Current Property Type: Single-family residential

Primary Architectural Style: Minimal Traditional

Building Envelope

Setting: set back

Height: 1-story

Plan: irregular

Primary Façade Composition: asymmetrical

Type of Construction: wood frame

Wall Cladding: brick masonry; stucco, smooth

Roof

Roof Form: hipped

Roof Cladding: composition shingle

Roof Details: eaves, open; exposed rafter tails; exterior chimney, brick

Entrance(s)

Primary Entry Type: stoop

Primary Entry Materials & Details: posts, wood; piers, brick; flooring, brick; steps, brick; light fixtures

Primary Door Type & Material: single door; plank door; wood

Primary Door Details: speakeasy

Windows

Window Grouping & Type 1: tripartite; fixed; casement

Window Materials 1: non-original material

Window Details 1: multi-light

Window Grouping & Type 2: paired; casement

Window Materials 2: non-original material

Window Details 2: multi-light

Window Grouping & Type 3: single; sliding, horizontal

Window Materials 3: non-original material

Window Details 3: multi-light

Related Features

Related Features: garage, detached; driveway, brick; driveway, concrete; lawn; walkway, brick pavers; retaining wall, concrete; retaining wall, brick

Alterations

Alterations: windows replaced, all; wall cladding added/replaced; garage door replaced; driveway gate added/replaced; retaining wall added

Character-defining Features: none identified

Integrity: low

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other:

*P5a. Photograph or Drawing (Photograph required for buildings, structures, or objects)



P5b. Description of Photo: (view, date, accession #) View northeast, 4/4/2025

*P6. Date Constructed/Age and Sources 1937 (County Assessor)

☒ Historic ☐ Prehistoric ☐ Both

*P7. Owner and Address: Not Recorded

*P8. Recorded by: (Name, affiliation, and address) Architectural Resources Group, 360 E. 2nd Street, Suite 225 Los Angeles, CA 90012

*P9. Date Recorded: 4/4/2025

*P10. Survey Type: (Describe)

☒ Intensive ☐ Reconnaissance

*P11. Report Citation: (Cite survey report and other sources or enter "none".) ARG, Cleveland Knoll Historic District Report, (prepared for the City of Glendale Planning Division, 2025).

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure & Object Record
☐ Archaeological Record ☒ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photographic Record ☐ Other (List)